



CERTIFICATE NUMBER
**Commercial Vehicle Inspection Certificate
Traffic Safety Act**
**PART 1 - VEHICLE OWNER AND VEHICLE
IDENTIFICATION**

Vehicle Type:	Trailer	Seating Capacity:	
GVW:	kg	Brake Type:	Air
Owner Name:	LCOS HEAVY HAUL LTD		
Address:	#1 3603-53 ST		
City:	ATHABASCA	Province:	AB
Postal Code:	T9S1A9		
Telephone Number:	(780) 675-9613		
Vehicle Identification Number:	2M5131614F1147824		
Make:	MANAC	Model:	53'TRIDEM FLATD
Year:	2015	Unit Number:	HB824
Odometer:	KM	Licence Plate Number:	4WL272
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE
PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
All-Pro Truck & Trailer Repair Ltd.	11562
Inspection Technician Name:	Technician Number:
Brittany McCabe	C1021
Inspection Technician Signature:	
Inspection Date:	2025/10/27

**COMMERCIAL VEHICLE RECORD OF INSPECTION
TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY**

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Type of Vehicle										Gross Vehicle Weight registered											
Trailer										kg											
Vehicle Information																					
VIN	2	M	5	1	3	1	6	1	4	F	1	1	4	7	8	2	4				
Unit Number HB824				Year 2015				Make MANAC				Model 53'TRIDEM FLATD				Odometer					
Registered Owner's Name LCOS HEAVY HAUL LTD																Plate Number 4WL272					
Address #1 3603-53 ST										Postal Code T9S1A9				Phone Number (780) 675-9613							

Drum Brakes:	B-Wheel-on Full Inspection	Disc Brakes:
---------------------	-----------------------------------	---------------------

		<u>LEFT</u>	<u>FRONT</u>	<u>RIGHT</u>		
100 psi	100 psi	419.86 mm	Drums/Rotors	419.78 mm	100 psi	100 psi
16 mm	16 mm	20 mm	Linings/Pads	20 mm	7 mm	8 mm
		38.10 mm	Push Rod Travel	38.10 mm		
100 psi	100 psi	419.78 mm	Drums/Rotors	420.11 mm	100 psi	100 psi
17 mm	17 mm	20 mm	Linings/Pads	17 mm	17 mm	16 mm
		38.10 mm	Push Rod Travel	38.10 mm		
100 psi	100 psi	419.73 mm	Drums/Rotors	419.91 mm	100 psi	100 psi
16 mm	16 mm	20 mm	Linings/Pads	18 mm	15 mm	15 mm
		38.10 mm	Push Rod Travel	38.10 mm		
psi	psi	mm	Drums/Rotors	mm	psi	psi
mm	mm	mm	Linings/Pads	mm	mm	mm
		mm	Push Rod Travel	mm		
psi	psi	mm	Drums/Rotors	mm	psi	psi
mm	mm	mm	Linings/Pads	mm	mm	mm
		mm	Push Rod Travel	mm		
psi	psi	mm	Drums/Rotors	mm	psi	psi
mm	mm	mm	Linings/Pads	mm	mm	mm
		mm	Push Rod Travel	mm		

Park Brake Lining Left 20 mm Right 17 mm Trans n/a mm
 Wheel Torque Checked ☒ Inner n/a ft lbs Outer 500 ft lbs

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

Section 1 - Power Train

Component	P	F	NA	Component	P	F	NA
1.2. Exhaust System		✓		1.12. Gasoline or Diesel Fuel System (LPG, CNG, & LNG) * SEE APPENDIX A*			✓

NOTES:

APPENDIX "A"

Component	P	F	NA	Component	P	F	NA
A.1. Liquefied Petroleum Gas (LPG or Propane) Fuel System		✓		A.3. Liquefied Natural Gas (LNG) Fuel System			✓
A.2. Compressed Natural Gas (CNG) Fuel System		✓					

NOTES:

Section 2 - Suspension

Component	P	F	NA	Component	P	F	NA
2.1. Suspension & Frame Attachments	✓			2.5. Air Suspension	✓		
2.2. Axle Attaching & Tracking Components	✓			2.6. Self-Steer & Controlled-Steer Axle			✓
2.3. Axle & Axle Assembly	✓			2.7. Shock Absorber/Strut Assembly	✓		
2.4. Spring & Spring Attachment			✓				

NOTES:

Section 3H - Hydraulic Brakes

Component	P	F	NA	Component	P	F	NA
3H.1. Hydraulic System Components		✓		3H.10. Electric Brake System			✓
3H.6. Air-Over-Hydraulic Brake System		✓		3H.12. Drum Brake System Components			✓
3H.7. Surge Brake Controller		✓		3H.13. Disc Brake System Components			✓
3H.8. Vacuum System		✓		3H.19. Brake Performance			✓
3H.9. Air-Boosted Trailer Brake System		✓					

NOTES:

Section 3A - Air Brakes

Component	P	F	NA	Component	P	F	NA
3A.3. Air System Leakage	✓			3A.16. S-Cam Drum Brake System	✓		
3A.4. Air Tank	✓			3A.17. Brake Shoe Travel (Wedge Brakes)			✓
3A.8. Brake Valves & Controls	✓			3A.18. Disc Brake System Components			✓
3A.12. Parking Brake & Emergency Application	✓			3A.20. Anti-Lock Brake System (ABS)	✓		
3A.13. Air System Components	✓			3A.22. Stability Control System (ESC) or (RSS)			✓
3A.14. Brake Chamber	✓			3A.23. Brake Performance	✓		
3A.15. Drum Brake System Components	✓						

NOTES:

air tank valve leaking , #1rh, #2l+r #3rh broken springs in pots, needs glad hands** fixed

Section 4 - Steering

Component	P	F	NA	Component	P	F	NA
4.1. Steering Control & Linkage		✓		4.5. Self Steer & Controlled-Steer Axle			✓
4.4. Kingpin		✓					

NOTES:

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

Section 5 - Instruments and Auxiliary Equipment

Component	P	F	NA	Component	P	F	NA
5.1. Fire Extinguisher		✓					

NOTES:

Section 6 - Lamps

Component	P	F	NA	Component	P	F	NA
6.1. Required Lamps	✓			6.3. Retro-Reflective Marking	✓		
6.2. Reflex Reflector	✓						

NOTES:

If+ rr corner reflectors missing, rh signal out** fixed

Section 7 - Electrical System

Component	P	F	NA	Component	P	F	NA
7.1. Wiring	✓			7.3. Trailer Cord (output to towed vehicle)	✓		
7.2. Battery		✓					

NOTES:

Section 8 - Body

Component	P	F	NA	Component	P	F	NA
8.5. Cargo Body	✓			8.11. Refrigeration/Heater Unit Fuel System			✓
8.6. Frame Rails & Mounts	✓			8.21. Fender/Mud Flap	✓		
8.7. Unitized Body Elements		✓		8.22. Landing Gear on Trailer	✓		
8.8. Cab or Cargo Door		✓		8.23. Sliding Axle Assembly (Sliding Bogie)	✓		
8.9. Cargo Tank or Vessel		✓		8.24. Aerodynamic Device & Attachment			✓
8.10. Body, Device or Equipment Attached or Mounted to the Vehicle	✓			8.25. Rear Impact Guard (RIG)			✓

NOTES:

Section 9 - Tires and Wheels

Component	P	F	NA	Component	P	F	NA
9.1. Tire Tread Depth	✓			9.7. Wheel/Rim	✓		
9.2. Tire Tread Condition	✓			9.8. Multi-Piece Wheel/Rim	✓		
9.3. Tire Sidewall & Manufacturer Markings	✓			9.9. Spoke Wheel/Demountable Rim System	✓		
9.4. Tire Inflation Pressure	✓			9.10. Disc Wheel System	✓		
9.5. Wheel Hub	✓			9.11. Wheel Fasteners (Nuts, Bolts, & Studs)	✓		
9.6. Wheel Bearing	✓						

NOTES:

tire pressures needs adj. #1+#2rh + #1lh wheel seals leaking** fixed

Section 10 - Couplers and Hitches

Component	P	F	NA	Component	P	F	NA
10.1. Hitch Assembly, Structure & Attaching Components	✓			10.6. Automated Coupling Device			✓
10.2. Secondary Attachment (Safety Chain or Cable)		✓		10.7. Fifth Wheel Coupler	✓		
10.3. Pintle Hook, Pin Hitch, or Coupler Hitch		✓		10.8. Oscillating Fifth Wheel Coupler			✓
10.4. Ball Type Hitch		✓		10.9. Ball-Bearing Type Turntable on Trailer			✓
10.5. Roll-Coupling Hitch		✓					

**COMMERCIAL VEHICLE RECORD OF INSPECTION
TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY**

NOTES:

Certification

The Vehicle for which this Record of Inspection is issued has **PASSED** (Certificate #8430613) the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 211/2006 and the applicable Inspection Manual.

Date of Inspection	Technician Number	Facility Number	Signature
2025/10/27	C1021	11562	

Customer Acknowledgment

I understand if a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the initial inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.

Date (Year/Month/Day)

2025/10/27

Customer Signature

