

LCOS

Alberta Government

CV8430608



80087100008430608

CERTIFICATE NUMBER

**Commercial Vehicle Inspection Certificate
Traffic Safety Act****PART 1 - VEHICLE OWNER AND VEHICLE
IDENTIFICATION**

Vehicle Type:	Trailer	Seating Capacity:	
GVW:	kg	Brake Type:	Air
Owner Name:	LCOS HEAVY HAUL LTD		
Address:	#1 3603-53 ST		
City:	ATHABASCA	Province:	AB
		Postal Code:	T9S1A9
Telephone Number:	(780) 675-9613		
Vehicle Identification Number:	2M5131619D1137206		
Make:	Manac	Model:	Flatdeck
Year:	2013	Unit Number:	HB206
Odometer:	KM	Licence Plate Number:	4WM419
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE**PART 2 - CERTIFICATION**

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Facility Number:
All-Pro Truck & Trailer Repair Ltd.	11562
Inspection Technician Name:	Technician Number:
Pascal Pealey	D1617
Inspection Technician Signature:	
Inspection Date:	2025/10/17

**COMMERCIAL VEHICLE RECORD OF INSPECTION
TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY**

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Type of Vehicle										Gross Vehicle Weight registered									
Trailer										kg									
Vehicle Information																			
VIN	2	M	5	1	3	1	6	1	9	D	1	1	3	7	2	0	6		
Unit Number HB206			Year 2013			Make Manac			Model Flatdeck			Odometer							
Registered Owner's Name LCOS HEAVY HAUL LTD															Plate Number 4WM419				
Address #1 3603-53 ST										Postal Code T9S1A9					Phone Number (780) 675-9613				

Drum Brakes:	A-Full Inspection with Drum Removed	Disc Brakes:
---------------------	--	---------------------

		<u>LEFT</u>	<u>FRONT</u>	<u>RIGHT</u>		
100 psi	100 psi	420.11 mm	Drums/Rotors	419.86 mm	100 psi	100 psi
17 mm	14 mm	17 mm	Linings/Pads	19 mm	15 mm	15 mm
		38.1 mm	Push Rod Travel	38.1 mm		
100 psi	100 psi	419.86 mm	Drums/Rotors	420.11 mm	100 psi	100 psi
17 mm	17 mm	17 mm	Linings/Pads	19 mm	16 mm	16 mm
		38.1 mm	Push Rod Travel	38.1 mm		
100 psi	100 psi	420.14 mm	Drums/Rotors	419.86 mm	100 psi	100 psi
17 mm	16 mm	18 mm	Linings/Pads	19 mm	16 mm	16 mm
		38.1 mm	Push Rod Travel	38.1 mm		
psi	psi	mm	Drums/Rotors	mm	psi	psi
mm	mm	mm	Linings/Pads	mm	mm	mm
		mm	Push Rod Travel	mm		
psi	psi	mm	Drums/Rotors	mm	psi	psi
mm	mm	mm	Linings/Pads	mm	mm	mm
		mm	Push Rod Travel	mm		
psi	psi	mm	Drums/Rotors	mm	psi	psi
mm	mm	mm	Linings/Pads	mm	mm	mm
		mm	Push Rod Travel	mm		

Park Brake Lining Left 17 mm Right 19 mm Trans n/a mm
 Wheel Torque Checked ☒ Inner n/a ft lbs Outer 500 ft lbs

COMMERCIAL VEHICLE RECORD OF INSPECTION
TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

Section 1 - Power Train							
Component	P	F	NA	Component	P	F	NA
1.2. Exhaust System		✓		1.12. Gasoline or Diesel Fuel System (LPG, CNG, & LNG) * SEE APPENDIX A*			✓

NOTES:

APPENDIX "A"							
Component	P	F	NA	Component	P	F	NA
A.1. Liquefied Petroleum Gas (LPG or Propane) Fuel System		✓		A.3. Liquefied Natural Gas (LNG) Fuel System			✓
A.2. Compressed Natural Gas (CNG) Fuel System		✓					

NOTES:

Section 2 - Suspension							
Component	P	F	NA	Component	P	F	NA
2.1. Suspension & Frame Attachments	✓			2.5. Air Suspension	✓		
2.2. Axle Attaching & Tracking Components	✓			2.6. Self-Steer & Controlled-Steer Axle			✓
2.3. Axle & Axle Assembly	✓			2.7. Shock Absorber/Strut Assembly	✓		
2.4. Spring & Spring Attachment			✓				

NOTES:

Section 3H - Hydraulic Brakes							
Component	P	F	NA	Component	P	F	NA
3H.1. Hydraulic System Components			✓	3H.10. Electric Brake System			✓
3H.6. Air-Over-Hydraulic Brake System			✓	3H.12. Drum Brake System Components			✓
3H.7. Surge Brake Controller			✓	3H.13. Disc Brake System Components			✓
3H.8. Vacuum System			✓	3H.19. Brake Performance			✓
3H.9. Air-Boosted Trailer Brake System			✓				

NOTES:

Section 3A - Air Brakes							
Component	P	F	NA	Component	P	F	NA
3A.3. Air System Leakage	✓			3A.16. S-Cam Drum Brake System	✓		
3A.4. Air Tank	✓			3A.17. Brake Shoe Travel (Wedge Brakes)			✓
3A.8. Brake Valves & Controls	✓			3A.18. Disc Brake System Components			✓
3A.12. Parking Brake & Emergency Application	✓			3A.20. Anti-Lock Brake System (ABS)	✓		
3A.13. Air System Components	✓			3A.22. Stability Control System (ESC) or (RSS)			✓
3A.14. Brake Chamber	✓			3A.23. Brake Performance	✓		
3A.15. Drum Brake System Components	✓						

NOTES:

#1 air tank valve leaking, abs valve leaking, service air line fitting leaking at the abs valve, front q/r valve leaking fix,

Section 4 - Steering							
Component	P	F	NA	Component	P	F	NA
4.1. Steering Control & Linkage			✓	4.5. Self Steer & Controlled-Steer Axle			✓
4.4. Kingpin			✓				

NOTES:

Section 10 - Couplers and Hitches							
Component	P	F	NA	Component	P	F	NA
10.1. Hitch Assembly, Structure & Attaching Components	✓			10.6. Automated Coupling Device			✓
10.2. Secondary Attachment (Safety Chain or Cable)		✓		10.7. Fifth Wheel Coupler	✓		
10.3. Pintle Hook, Pin Hitch, or Coupler Hitch		✓		10.8. Oscillating Fifth Wheel Coupler			✓
10.4. Ball Type Hitch		✓		10.9. Ball-Bearing Type Turntable on Trailer			✓
10.5. Roll-Coupling Hitch		✓					

**COMMERCIAL VEHICLE RECORD OF INSPECTION
TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY**

NOTES:

Certification

The Vehicle for which this Record of Inspection is issued has **PASSED** (Certificate #8430608) the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 211/2006 and the applicable Inspection Manual.

Date of Inspection

2025/10/17

Technician Number

D1617

Facility Number

11562

Signature

Customer Acknowledgment

I understand if a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the initial inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.

Date (Year/Month/Day)

2025/10/17

Customer Signature